

## WINTER PROTOCOL

It is important for Pandser and Premiumfol adhesives and sealants to be transported, stored and processed in frost-free conditions. At the moment and also in the coming weeks, this will be a hot topic. At temperatures below 5°C, we advise you to take precautions.



### PRECAUTIONS

The adhesives and sealants are designed for a flawless process, but temperature and humidity can affect the gluing process. Consider factors such as open time, drying time, clamping time and viscosity.

To prevent problems during the adhesive process, it is necessary to take the right precautions with regard to transport, storage and processing. We, from Berdal and our transport partners ensure that the products arrive at your premises in the right way.

It is up to you to ensure the minimum temperature during storage and processing.

- ✔ We advise you to transport, store and process adhesives and sealants in a frost-free environment.
- ✔ Do not place storage directly on the cold floor.
- ✔ Make sure the minimum temperature is above 5°C.
- ✔ Before processing, always check the packaging or the Technical Data Sheets for the correct processing temperatures.

### MORE INFORMATION

Do you have any questions and/or comments?  
Please contact Berdal.

**Berdal Rubber & Plastics BV**  
Bedrijvenpark Twente 193  
7602 KG Almelo  
The Netherlands  
+31(0)546 - 579 581

